

Inspection Photos



View of structure facing north.



View of structure facing east.





View of soffit.



View of severe spall on central soffit.