

SCHEDULE 'B'

Heritage Conservation and Maintenance Plan – D'Orr LePan House

Building Elevation:	Item No.	Historic Feature:	Description of Feature:	Current Condition	Description of Work	Anticipated Completion Date
NSEW	1	Exterior Walls	Raised buff arches, radiating voussoirs surrounding the head of the windows, raised buff quoins, two tall decorated single stack brick chimneys, robust brick porch	Good	Repointing & repair when and as required	Ongoing
NSEW	2	Exterior Walls	1 ½ storey red brick stretcher bond walls	Good	Repointing & repair when and as required	Ongoing
NSEW	3	Roof	Truncated hip roof, pediment dormers set in all four faces of the roof	Good	Reshingling & repair when and as required	Ongoing
NSEW	4	Fenestration	all wood sash windows, dormer windows	Good	Reglazing, repainting & repair when and as required	Ongoing